## **DATASHEET**





## CSP 34-S-1-01

- Actuation from side
- actuator code 1
- Sensor and actuator must be ordered separately.

Schmersal, Inc., 115 E Stevens Ave, Suite 208, Valhalla, NY 10595

The details and data referred to have been carefully checked. Images may diverge from original. Further technical data can be found in the manual. Technical amendments and errors possible.

Generated on: 7/4/2025, 3:14 PM